



Program Manager <applications@worldconnect-us.org>

Progress Report Follow-up

Samuel Onyeledo <beamsammy@gmail.com>

Sun, Mar 7, 2021 at 7:29 PM

To: Program Manager <applications@worldconnect-us.org>

Hello Sarah,

Thank you for your email.

Yes, the World Connect grant included the borehole, four toilets and five handwashing points (i.e. one in each of the toilets and one at a strategic point in the school).

The grant also included floor tiles for some of the toilets and piping. The World Connect grant did not include the security measures (fencing and barbed wires).

The borehole donated by Leadway Assurance in the school was installed at a farther location than where we had envisaged during the grant application. This was as a result of the geophysical exploration by the borehole installation company. Hence, the need for additional piping to connect the toilets and handwashing points from the new location. This is the additional piping added as a result of the leveraged investment.

Other elements added include two additional toilets and three additional handwashing points (i.e. one in each of the additional toilets and one at another strategic location in the school). In total, we now have 8 handwashing points (one in each of the six toilets and two at strategic positions in the school).

We also added the security measures and interlocks (brick tiles) for the toilet area. These were also not provided for in the grant.

For better clarification, I have attached pictures of the elements explained in this mail, having named each file accordingly.

Sorry for the wordy email. I would be glad to provide additional clarification if needed.

Warm regards

Samuel Chinonso Onyeledo

Alumnus

Teach For Nigeria

NNDC mall, Waff Road, Kaduna, Nigeria

teachfornigeria.org

+2348061532861

[Quoted text hidden]

12 attachments



Security fencing_compress76.jpg
667K



Connecting pipes to water source_compress30.jpg
565K



Before security fencing_compress25.jpg
609K



Toilet area entrance before intelocks_compress46.jpg
470K



Piping_compress17.jpg
621K



Toilet area after intelocks_compress43.jpg
369K



Interlocks in toilet area_compress20.jpg
524K



Interlocks and security fencing_compress55.jpg
464K



Toilet area before interlocks 1_compress80.jpg
775K



Before floor tiling_compress50.jpg
347K



After floor tiling_compress1.jpg
516K



Connecting pipes to water source 1_compress21.jpg
569K