

REHABILITATION OF THE KPATILI SHEA CENTRE

Kpatili- Ghana, Northern Region

October 2023- March 2024





The group leader and secretary being briefed of grant contract.



The president of the group signing the contract



Planning with the group for rehabilitation



Cracked windows



Cracked window side.



Hole in the left side of

Taking out the old non-functional wooden windows frames and replacing with metal frames



All wooden windows replaced.

Plastering of walls and floor. And extended the workplace to make way for a water



Creating a water waste collection point.



75 mm diameter metal poles/ pillars inserted to support roof.

More plastering of inside walls and 75 mm diameter metal poles to support the roof.



Removing of all leaking roofing sheets and rotten trusses/wood and replacing entire





Inside painted and all flooring done.





Sign board erected at the entrance into the community.



Signboard made to pin the top of the building.



Outside of building painted